

Commander, Eighth Coast Guard District (oan)
 Hale Boggs Federal Building, Room 1230
 500 Poydras Street, New Orleans, LA 70130-3310
 Telephone: (504) 589-6277
 (Business Hours 7:45 a.m. – 4:15 p.m. Monday - Friday)
 (Nights, Weekends, Holidays) - (504) 589-6225

**U.S. Department of
 Homeland Security**

**United States
 Coast Guard**



8TH DISTRICT LOCAL NOTICE TO MARINERS MISSISSIPPI RIVER SYSTEM WEEKLY SUPPLEMENT

Western Rivers
 LIGHT LIST VOLUME V
 NOTICE NUMBER 08-04
 February 24, 2004

The Local Notice to Mariners consists of a Monthly Edition and Weekly Supplements. The Monthly Edition is published the first week of each month, and Weekly Supplemental Editions are published in the intervening weeks. Weekly Supplemental Editions contain only new information; however, ongoing events/conditions published in Weekly Supplements at times are readvertised in the following Monthly Edition. Light list corrections printed in the Weekly Supplemental Editions are not repeated in Monthly Editions.

The Current Monthly Edition is Notice Number 05-04.

LIGHT LIST REFERENCE: COMDTPUB P16502.4, Vol. V, 2002 Edition.

CONTENTS: Rivers are listed in alphabetical order and are included only when there is information to report.

NIS WATCHSTANDER PHONE	(703) 313-5900 24-HOURS A DAY
INTERNET ADDRESSES	http://www.navcen.uscg.gov/
ZERO NOTICE INTERNET ADDRESS	http://www.navcen.uscg.gov/
WESTERN RIVERS LNM VIA INTERNET	http://www.navcen.uscg.gov/lnm/d8mrs
WESTERN RIVERS LIGHT LIST VIA INTERNET	http://www.navcen.uscg.gov/pubs/LightLists/V5COMPLETE.pdf

BROADCAST NOTICE TO MARINERS COVERED IN THIS EDITION

ORIGINATING UNITS	BEGINNING BNMS	THROUGH	ENDING BNMS
GROUP UPPER MISSISSIPPI RIVER	0024-04 (UM)	THROUGH	0033-04 (UM)
GROUP LOWER MISSISSIPPI RIVER	0039-04 (LM)		0045-04 (LM)
GROUP OHIO VALLEY	0090-04 (OV)		0113-04 (OV)
OB DWRO	0004-04 (OB)		0010-04 (OB)

SPECIAL NOTICES

MISSISSIPPI RIVER SYSTEM AIDS TO NAVIGATION	Due to swift currents, flowing ice and/or fast ice, floating aids to navigation may be dragged off station, diving, submerged, missing or not properly marking the channel. The aids reflective material may be ineffective due to ice. Mariners are reminded not to solely rely on buoys for safe navigation due to these factors. (07-04/D8)
RADIOTELEPHONE SERVICE 2182.0 KHZ	The U.S. Coast Guard International Distress and Calling Radiotelephone Service on the frequency 2182.0 kHz may be operating at reduced power and sensitivity due to shoreside radio infrastructure problems. Action is underway to correct these problems. The U.S. Coast Guard is operating a medium frequency Digital Selective Calling Distress and Safety Service on a trial operational basis only. A Global Maritime Distress and Safety System (GMDSS) Sea Area A2 will not be declared in U.S. waters until shoreside radio infrastructure problems can be corrected. (02-04/G-OPN)
WATERWAY ANALYSIS AND MANAGEMENT SYSTEM STUDY OHIO RIVER (0.0-981.0) BIG SANDY RIVER (0.0-7.2) GREEN RIVER (0.0-149.0)	The U. S. Coast Guard is conducting a Waterways Analysis and Management System (WAMS) study of the Ohio River, Big Sandy River and Green River. The study focuses on the areas aids to navigation system, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future development projects. This review period will run through February 2004. Any interested company or individual wishing to provide comments should contact the following address. You can also receive user surveys and WAMS questionnaires to help in the study by E-Mail. Mail Commander U. S. Coast Guard Group Ohio Valley 600 Martin Luther King Jr. PL. Rm. 421 Louisville, KY 40202-2245 PH: (502) 582-6439 #234 E-Mail WAMS System User Questionnaire E-Mail: wgibson@gruohiovalley.uscg.mil (44-03/OV 48-03 49-03 50-03 51-03 52-03)

SPECIAL NOTICES CONTINUED

ILLINOIS WATERWAY SAFETY ADVISORY UPDATE	The COTP's St. Louis, MO and Chicago, Illinois River Carriers Association and the ACOE have issued the following tow limitations: All mariners are to avoid meeting or passing situations on Peoria Lake between Mile 179.0 and 169.0. This is to ensure the integrity of the existing ice trail across Peoria Lake to aid in safe navigation. The previous restriction from the Peoria Narrows, Mile 165.0 to Babbs Slough, Mile 184.0, regarding the length of tows, has been lifted due to warmer weather. (05-04/0012UM 06-04/0023UM 07-04/0024UM 08-04/0029UM)
ILLINOIS WATERWAY AIDS TO NAVIGATION	Buoys between approximate Miles 291.1 and 0.0, should be considered unreliable due to ice. Ice floes render reflective material ineffective or drag buoys off station. Areas, which have experienced icing conditions, may have few if any buoys remaining. Mariners are urged to exercise extreme caution when transiting the area. (05-04/0014UM)
OHIO RIVER MONONGAHELA RIVER AIDS TO NAVIGATION	Due to recent ice and high water conditions on the Ohio Rivers, from Pittsburgh, PA. to Long Bottom, vicinity of Mile 210.0, and the entire Monongahela River, aids to navigation may be missing or not properly marking the channel. Mariners are urged to exercise extreme caution when transiting the area. (05-04/0084OV)

DISCREPANCIES AND DISCREPANCIES CORRECTED

The rivers are marked with numerous unlisted and unlighted buoys, which are periodically relocated to mark the navigational channel due to changing river conditions. To report Aids to Navigation discrepancies contact the nearest Coast Guard Office.
 Coast Guard Group Ohio Valley (800) 253-7465
 Coast Guard Group Upper Mississippi River (319) 524-7511 Extension 4
 Coast Guard Group Lower Mississippi River (901) 544-3912 Extension 122

FEDERAL AID DISCREPANCIES	LLNR	MILE	BANK	AID NAME	STATUS	LNMB/NM
LOWER MISSISSIPPI RIVER	9530	953.5	L/B	UPPER RIVER RANGE LIGHT	LT EXT	08-04/0110OV
	10515	683.4	L/B	MHOON BEND DAYBEACON	LT EXT	08-04/0047LM
RED RIVER	29231.85	180.2	L/B	POSEY BRANCH DAYBEACON	DBN DEST/DBN DMGD	08-04/0044LM
TENNESSEE RIVER	30865	483.4	L/B	DENNY BLUFF LIGHT	LT EXT	08-04/0093OV
FEDERAL AID DISCREPANCIES CORRECTED	LLNR	MILE	BANK	AID NAME	STATUS	LNMB/NM
CUMBERLAND RIVER	4335	65.2	R/B	DEVILS POTATO HILL LIGHT	REBUILT/RECOVERED	08-04
LOWER MISSISSIPPI RIVER	11490	393.8	L/B	BONDURANT TOWHEAD LIGHT	REBUILT/RECOVERED	08-04
OHIO RIVER	28170	932.5	R/B	KINKAID LANDING LIGHT	REBUILT/RECOVERED	08-04
TEMPORARY CHANGES	LLNR	MILE	BANK	AID NAME	STATUS	LNMB/NM
NONE						
TEMPORARY CHANGES CORRECTED	LLNR	MILE	BANK	AID NAME	STATUS	LNMB/NM
NONE						
PRIVATE AID DISCREPANCIES	LLNR	MILE	BANK	AID NAME	STATUS	LNMB/NM
NONE						
PRIVATE AID DISCREPANCIES CORRECTED	LLNR	MILE	BANK	AID NAME	STATUS	LNMB/NM
NONE						

PROPOSED CHANGES IN AIDS TO NAVIGATION

None						
------	--	--	--	--	--	--

ADVANCED CHANGES IN AIDS TO NAVIGATION

None						
------	--	--	--	--	--	--

GENERAL INFORMATION

LOWER MISSISSIPPI RIVER	MILE 640.5 – MILE 639.5 AIDS TO NAVIGATION UPDATE	Two nun buoys between approximate Miles 640.5 and 639.5, Island 63, previously reported diving and unreliable, are no longer diving. (07-04/0033LM 08-04/LM)
	MILE 627.0 – MILE 626.0 AIDS TO NAVIGATION UPDATE	Three nun buoys between approximate Miles 627.0 and 626.0, Sunflower, previously reported diving and unreliable, are no longer diving. (07-04/0035LM 08-04/LM)
	MILE 621.5 AIDS TO NAVIGATION UPDATE	A nun dike buoy in the vicinity of Mile 621.5, Island 67, previously reported diving and unreliable, is no longer diving. (07-04/0034LM 08-04/LM)
	MILE 420.1 – MILE 418.3 AIDS TO NAVIGATION	Four can buoys have been reported diving or missing between approximate Miles 420.1 and 418.3. Mariners are urged to exercise extreme caution when transiting the area. (08-04/0045LM)
UPPER MISSISSIPPI RIVER	MILE 51.6 BRIDGE LIGHTING UPDATE	Bill Emerson Memorial Bridge: The superstructure will be illuminated from dusk to midnight starting February 21, 2004. The decorative lights can be extinguished for 45 minutes by dialing (573) 335-0642 and entering identification number 1 followed by the # key. Then terminate the call. (07-04/OB 08-04/OB)
OHIO RIVER	MILE 170.5 – MILE 171.4 CHANNEL CONDITION	Shoaling and toppled trees have been reported between approximate Mile 170.5 and 171.4, LDB, Marietta Island, due to a landslide. Two nun buoys have been established in the area. Mariners are urged to exercise extreme caution when transiting the area. (07-04/0091OV)
TENNESSEE RIVER	MILE 206.0 AIDS TO NAVIGATION	Several can buoys have been reported missing in the vicinity of Mile 206.0. Mariners are urged to exercise extreme caution when transiting the area. (08-04/0092OV)

GENERAL INFORMATION/CONTINUED

TENNESSEE RIVER CONTINUED	MILE 22.4 L/D REPAIR	Continuing until further notice, work is being conducted to repair a malfunctioning guidewall at the Kentucky L/D Upstream Guidewall in the vicinity of Mile 22.4. All downbound tows should contact the Lockmaster prior to arrival for lockage instructions. Mariners should expect intermittent delays during periods of repair. Mariners are urged to exercise extreme caution when transiting the area. (08-04/01130V)
--------------------------------------	---------------------------------	--

CORRECTIONS TO LIGHT LIST, VOLUME V; MISSISSIPPI RIVER SYSTEM, 2002 EDITION.

(* Denotes the column in which a correction has been made or new information added.)

(1) <u>No.</u>	(2) <u>Name and Location</u>	(3) <u>Mile</u>	(4) <u>Bank</u>	(5) <u>Characteristic</u>	(6) <u>Structure/Daymark</u>		(7) <u>Remarks</u>	<u>LNM</u>
None								

ENCLOSURES

None: